

# شهادة فحص مركبة Vehicle Test Certificate



## شهادة فحص مركبة Vehicle Test Certificate

This Inspection Certificate is valid and shows the vehicle condition at the time of the inspection only. Al Mumayaz Vehicle Testing doesn't guarantee the vehicle condition as soon as it leaves the inspection station and from then on, the inspection is considered invalid. Al Mumayaz Vehicle Testing is not responsible for the hidden defects in the vehicle, according to this Al Mumayaz does not guarantee the vehicle validity for registration.

شهادة الفحص هذه تظهر حالة المركبة وقت الفحص فقط و تعتبر الشهادة غير سارية بمجرد خروج المركبة من حارة الفحص كما لا تضمن المميز لفحص المركبات حالة المركبة بمجرد خروجها من حارة الفحص المميز لفحص المركبات غير مسؤولة عن العيوب الخفية في المركبة كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل

Reference/Transaction #	115154	الرقم المرجعي	Site Name	Rashidiya (Pioneer)	اسم الموقع
Test Date	10/10/2022 11:09:05	تاريخ الفحص	ID NO	8	فحصت بواسطة
Test Type	COMPREHENSIVE TEST	نوع الفحص	Chassis Number	1N4BL4BV8LC163603	رقم الهيكل
Vehicle Status	Unregistered	رقم المركبة	Engine Number	NILL	رقم المحرك
Year of Manufacture	2020	سنة الصنع	Cylinders	4	عدد الاسطوانات
Vehicle Type	SALOON	نوع المركبة	Fuel Type	Petrol	نوع الوقود
Make/Model	NISSAN/ALTIMA	نوع/موديل المركبة	Mileage	52366	عدد الاميال
			Vehicle Color	BLACK	لون المركبة

Defect	Result	Remarks
--------	--------	---------

### AUTOMATIC TEST

Brake System	Passed	نظام الفرامل
Exhaust Gas Test	Passed	CO 0.010 HC 45.000 نظام العادم
Shock Absorber Test	Not tested	فحص امتصاص الصدمات

### VISUAL TEST

Suspension Crack or Bend Bushes	bushes worn out .	التوصيلات
Rear Left & Right Tyres	cracked	حالة الاطوار الحلقي من جهة اليسار و اليمين
Rust	cross member getting rust & portions floor .	الصداء
Bumpers	rad. support& bumper frame repaired .	الدعامية
Chassis frame condition	Front both side chassis repaired .	حالة الشاصي
All Glasses	rear left side window motor not working	النوافذ الجانبية
Side Safety Frame	left side running board & front fender frame& bulk head repaired .	اعمدت السلامة الجانبية
Others	warning light on .	أخرى
Need Wheel Alignment		ميزانية العجلات
Engine and Gear Box Performance OK		أداء المحرك وناقص الحركة جيد
Sign of Front Accident		وجود مؤشر لحادث في المقدمة

**الفحص الشامل  
Comprehensive Test**  
هذه الشهادة غير صالحة لأغراض تسجيل المركبات  
This Certificate is Not Valid for Vehicle Register

شهادة فحص مركبة  
Vehicle Test Certificate



A/C Condition

a/c ok

حالة نظام التكييف

Air Bag Damaged

حالة الوسادة الهوائية

Body Repainted

body portions repaired &  
repainted scratches

حالة صيغ المركبة

الفحص الشامل  
Comprehensive Test

هدد الشهادة غير صالحة لاغراض تسجيل المركبات  
This Certificate is Not Valid for Vehicle Register



# Test Certificate



Registration



RTA

✓ PASS

Plate Details :	--
Chassis No :	1N4BL4BV8LC163603
Vehicle Make :	NISSAN
Vehicle Model :	ALTIMA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	83954 Kms.
Origin : United States	Model Year : 2020
Gear Type : Automatic	Engine Size : 1800 CC
Engine No : NIL	Horse Power : --
Axles No : 2	Cylinders : 4
No Of Doors : 4	No Of Seats : 5
G. V. W. : 1800 Kgs.	Empty Weight : 1250 Kgs.

Certificate Number :	5-SHA-2022-17681703
Inspection Date :	21-09-2022
Certificate Print Date :	21-09-2022
Services :	Registration Test
Vehicle Testing Partner :	Shamil
Vehicle Testing Center :	Shamil Muhaisnah
Total Time Taken :	5 min 32 sec
Appointment Ref Number :	--
Start Time : 12:32	End Time : 12:38
Time :	Token No. : 173
Lane : 02	Prints No : 1
Attempt : 2	

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)

16790 KM	1193 L	3973 AED	2.9 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	1800	2500	

## Inspection Remarks:

FRONT BOTH SIDE FRAME MEMBERS REPAIRED. HAVING RTA AUTHORIZED PASSED CCM REPORT WORK ORDER # 2022-09-07-1 & LEFT SIDE RUNNING BOARD FRONT FENDER FRAME, BULK HEAD REPAIRED.

## Payment Details

Inspection Performed by 20855	Payment Method Cash	Transaction Number 17681703	Service Fees AED 70 Collected on 21/09/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Shouq Biro Karambakhsh

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصراً في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراس البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة تغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

