

شهادة فحص مركبة Vehicle Test Certificate



شهادة فحص مركبة Vehicle Test Certificate

Reference/Transaction #	93009	الرقم المرجعي	Site Name	Rashidiya (Pioneer)	اسم الموقع
Test Date	23/11/2021 13:40:21	تاريخ الفحص	ID NO	8	فحصت بواسطة
Test Type	COMPREHENSIVE TEST	نوع الفحص	Chassis Number	WMWZP3C53CT249890	رقم الهيكل
Vehicle Status	Unregistered	رقم المركبة	Engine Number	NILL	رقم المحرك
Year of Manufacture	2012	سنة الصنع	Cylinders	4	عدد الاسطوانات
Vehicle Type	COUPE	نوع المركبة	Fuel Type	Petrol	نوع الوقود
Make/Model	MINI COOPER/S COUPE	نوع/موديل المركبة	Mileage	115831	عدد الاميال
			Vehicle Color	GERY	لون المركبة

Defect	Result	Remarks
AUTOMATIC TEST		
Brake System	Passed	
Exhaust Gas Test	Passed	CO 0.540 HC 251.000
Shock Absorber Test	Passed	
VISUAL TEST		
Suspension Crack or Bend Bushes		bushes worn out.
Bumpers		refitted .
Transmission Condition		gear ok.
Others		w/s area repaired . - this car ok. for reg.
Chassis OK		
Engine Oil Leaking		eng. oil leak .
Engine Condition		eng. water & oil mix .
Sign of Front Accident		
A/C Condition		a/c ok.
Body Repainted		body repainted .

شهادة الفحص هذه تظهر حالة المركبة وقت الفحص فقط و تعتبر الشهادة غير سارية بمجرد خروج المركبة من حارة الفحص كما لا تضمن المميز لفحص المركبات حالة المركبة بمجرد خروجها من حارة الفحص المميز لفحص المركبات غير مسؤولة عن العيوب الخفية في المركبة كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل

This Inspection Certificate is valid and shows the vehicle condition at the time of the inspection only. Al Mumayaz Vehicle Testing doesn't guarantee the vehicle condition as soon as it leaves the inspection station and from then on, the inspection is considered invalid.

Comprehensive Test
This Certificate Is Not valid For Vehicle Register

شهادة فحص مركبة
Vehicle Test Certificate



Al Mumayaz Vehicle Testing is not responsible for the hidden defects in the vehicle, according to this Al Mumayaz does not guarantee the vehicle validity for registration.

الفحص الشامل
Comprehensive Test
هذه الشهادة غير صالحة لأغراض تسجيل المركبات
This Certificate Is Not Valid For Vehicle Register