## **Test Certificate**









| Custom Certificate:         | 12525367                |
|-----------------------------|-------------------------|
| Chassis No:                 | 1G1FB1RS7J0139518       |
| Vehicle Make :              | CHEVROLET               |
| Vehicle Model:              | CAMARO                  |
| Vehicle Class:              | Light Vehicle           |
| Body Type:                  | Coupe                   |
| Fuel:                       | Benzene                 |
| Color:                      | Red, Black              |
| Drive Direction:            | Left Hand Side          |
| Dimensions : (H x W x L)    | )xx                     |
| Current Odometer:           | 80763 Kms.              |
| Origin: United Stat         | es Model Year : 2018    |
| Gear Type : Automatic       | Engine Size: 3600 CC    |
| Engine No: NIL              | Horse Power:            |
| Axles No: 2                 | Cylinders: 6            |
| No Of Doors: 2              | No Of Seats: 4          |
| <b>G. V. W. :</b> 2600 Kgs. | Empty Weight: 2100 Kgs. |

Certificate Number: 5-110-2021-15199986 Inspection Date: 10-10-2021 Certificate Print Date : 10-10-2021 Services: Registration Test Vehicle Testing Partner: Shamil Vehicle Testing Center: Shamil Muhaisnah Total Time Taken: 12 min 40 sec Appointment Ref Number : --Start Time: 10:07 End Time: 10:20 Lane: Token No.: 113 Prints No: 1 Attempt: 1

#### Carbon footprint



Thank you! You are environment protector

### Estimated Vehicle Consumption (Rate in 12 Months)



13460 KM

year





Fuel cost per vear

Carbon footprint per year

#### **Parameter Readings**

Vehicle on Petrol CO Service brake imbalance on Service brake imbalance on Parking brake imbalance front axle between LHS and RHS Reading rear axle 1% 0.02 % 3 % Vehicle on Petrol HC Reading

### **Inspection Remarks:**

5 PPM VOL

FRONT LEFT SIDE FENDER FRAME, APRON, FENDER INNER MEMBER, WHEEL ARC REPAIRED & FLOOR MINOR DETACHED, CHANGE FRONT LEFT SIDE CONTROL ARM BOOT CUT, CHANGE REAR RIGHT SIDE TIRE OLD

# **Payment Details**

Inspection Performed by **Payment Method Transaction Number** Service Fees AED 170 Collected on 10/10/2021 12841 58681 - -Cash 15199986 **Parking Slot No Service Name** Attempt Received by Mona Medhat Abdelhadi Khaled **Registration Test** 

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهةً المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال .30 يوم من تأريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including the contract of the contselling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.