

شهادة فحص مركبة Vehicle Test Certificate



شهادة فحص مركبة Vehicle Test Certificate

This Inspection Certificate is valid and shows the vehicle condition at the time of the inspection only. Al Mumayaz Vehicle Testing doesn't guarantee the vehicle condition as soon as it leaves the inspection station and from then on, the inspection is considered invalid. Al Mumayaz Vehicle Testing is not responsible for the hidden defects in the vehicle, according to this Al Mumayaz does not guarantee the vehicle validity for registration.

شهادة الفحص هذه تظهر حالة المركبة وقت الفحص فقط و تعتبر الشهادة غير سارية بمجرد خروج المركبة من حارة الفحص كما لا تضمن المميز لفحص المركبات حالة المركبة بمجرد خروجها من حارة الفحص المميز لفحص المركبات غير مسؤولة عن العيوب الخفية في المركبة كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل

Reference/Transaction #	115305	الرقم المرجعي	Site Name	Rashidiya (Pioneer)	اسم الموقع
Test Date	11/10/2022 18:04:34	تاريخ الفحص	ID NO	8	فحصت بواسطة
Test Type	COMPREHENSIVE TEST	نوع الفحص	Chassis Number	WDDWF4CB7FR008703	رقم الهيكل
Vehicle Status	Unregistered	رقم المركبة	Engine Number	nil	رقم المحرك
Year of Manufacture	2015	سنة الصنع	Cylinders	4	عدد الاسطوانات
Vehicle Type	SALOON	نوع المركبة	Fuel Type	Petrol	نوع الوقود
Make/Model	MERCEDES/C 200	نوع/موديل المركبة	Mileage	228191	عدد الاميال
			Vehicle Color	GERY	لون المركبة

Defect	Result	Remarks	
AUTOMATIC TEST			
Brake System	Passed		نظام الفرامل
Exhaust Gas Test	Passed	CO 0.280 HC 155.000	نظام العادم
Shock Absorber Test	Not tested		فحص امتصاص الصدمات
VISUAL TEST			
Cover		under body covered - portion crack .	الغطاء
Front Left & Right Tyres		all tires crack & worn out	حالة الاطوار الامامي من جهة اليسار و اليمى
Rims		scratches	حالة الرنجات
Doors & Locks		right side doors, bonnet & trunk repaired - portion cover missing .	الأبواب والأقفال
Fenders		fenders repaired .	المذكار
Bumpers		bulk head repaired .	الدعامية
All Glasses		rear right side window motor n/w & front right noise /	النوافذ الجانبية
GCC Specification		YES .	مواصفات خليجية
Chassis OK			الشاصي بحالة جيدة
Engine and Gear Box Performance OK			أداء المحرك وناقص الحركة جيد
Sign of Front Accident			وجود مؤشر لحادث في المقدمة
A/C Condition		a/c ok	حالة نظام التكييف

**الفحص الشامل
Comprehensive Test**
هدد الشهادة غير صالحة لاغراض تسجيل المركبات
This Certificate is Not Valid for Vehicle Register

شهادة فحص مركبة
Vehicle Test Certificate

المصير
almumayaz
Vehicle Testing / لفحص المركبات

Digital Display Damaged/Warning
Lights

air bag warning light on .

أضواء التحذير / العرض الرقمي التالف

Body Repainted

body portions repaired &
repainted ,scratches

حالة صيغ المركبة

الفحص الشامل
Comprehensive Test
هدد الشهادة غير صالحة لأغراض تسجيل المركبات
This Certificate is Not Valid for Vehicle Register

Test Certificate



Registration



RTA

✓ PASS

Plate Details :	188731 Sharjah Private
Chassis No :	WDDWF4CB7FR008703
Vehicle Make :	MERCEDES
Vehicle Model :	C200
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Gray
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	--x--x--
Current Odometer :	228167 Kms.
Origin : South Africa	Model Year : 2015
Gear Type : Automatic	Engine Size : 2000 CC
Engine No : 2749203021...	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 2200 Kgs.	Empty Weight : 1500 Kgs.

Certificate Number :	1-SHA-2022-17821164
Inspection Date :	10-10-2022
Certificate Print Date :	10-10-2022
Services :	Renewal Test
Vehicle Testing Partner :	Shamil
Vehicle Testing Center :	Shamil Muhaisnah
Total Time Taken :	9 min 13 sec
Appointment Ref Number :	--
Start Time : 12:13	End Time : 12:22
Lane : 02	Token No. : 173
Attempt : 1	Prints No : 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)

17265 KM	1227 L	4135 AED	3.0 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 15 %	Service brake imbalance on rear axle 10 %	Parking brake imbalance between LHS and RHS 9 %	Vehicle on Petrol CO Reading 0.01 %
Vehicle on Petrol HC Reading 9 PPM VOL			

Inspection Remarks: UNDER BODY COVERED.PERFORM FRONT WHEEL ALIGNMENT.

Payment Details

Inspection Performed by 17771	Payment Method Cash	Transaction Number 17821164	Service Fees AED 170 Collected on 10/10/2022
Parking Slot No --	Service Name Renewal Test	Attempt 1	Received by Shouq Biro Karambakhsh

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

شامل
Shamil